



# 26' GROWING DOME TAPING THE VENTS

## CROSS SECTION OF VENT HINGE EDGE SHOWING TAPE



DRAWINGS NOT TO SCALE

## DETAILS OF VENT HINGE EDGE SHOWING ADDITIONAL TAPE REQUIRED ON TOP VENTS ONLY



IT IS IMPORTANT TO TAPE THE VENT HINGE SIDE WHEN THE VENT IS IN THE FULLY CLOSED POSITION